

To: Griswold, Hays[Griswold.Hays@epa.gov]
Cc: Allen Sorenson[Allen.Sorenson@state.co.us]; Kirstin Brown[Kirstin.Brown@state.co.us]
From: Way, Steven
Sent: Thur 7/30/2015 1:15:41 AM
Subject: Fwd: GK Exploration

FYI

Sent from my iPhone

Begin forwarded message:

From: "Matt Francis" <m.francis@erllc.com>
To: "Way, Steven" <way.steven@epa.gov>
Cc: "Petri, Elliott" <Elliott.Petri@WestonSolutions.com>
Subject: GK Exploration

Attached are some pics after Frank did some removal above the outlet pipe. Not sure how the depth is represented in the pictures, but he removed as far as the excavator would reach without additional ramping or parking on the adit – roughly 15-20. The last picture is from inside the pipe looking back towards the crap behind it. Appears to be a rather short pipe to me. In general, all the rock above and around the portal seems to be fractured chunks that come apart easily. We will likely be going back significantly to find something solid to set the 10' portal pipe against. That means we need to look at how the hillside might need to be removed/sloped/secured/etc.

Matt Francis

Environmental Restoration, LLC

303.994.6611

Confidentiality Warning: This e-mail and any attachments contain information intended only for the use of the individual or entity named above. If the reader of this e-mail is not the intended recipient or the employee or agent responsible for delivering it to the intended recipient, any dissemination, publication or copying of this e-mail is strictly prohibited. Although this email has been scanned for malware, the sender does not accept any responsibility for any loss, disruption or damage to your data or computer system that may

occur while using data contained in, or transmitted with, this e-mail. If you have received this e-mail in error, please immediately notify by return e-mail. Thank you.







